

## TITAN Meeting

**Date: Thursday July 12, 2007**      **Time: 15:00**

**Chairperson: Paul Delheij**

Others present: Mel Good, Don Dale, Fritz Buchinger

**RFQ:** Matthew Smith, Ryan Ringle

RFQ	<ul style="list-style-type: none"><li>- Put Li-11 gas through RFQ, tried to send beam through</li><li>- Took frequency scan to see what's coming out of source</li><li>- been 4 days, haven't stabilized</li><li>- Majority of gas through RFQ has mass = 38 – 40, Lithium definitely not dominant component.</li><li>- No manufacturer specifications for temperature or current (1.7A = reasonable?)</li><li>- For now, just knock up current and wait until impurities goes down.</li></ul>
MCP	<ul style="list-style-type: none"><li>- Discovered metal piece between feed-through and wall</li><li>- Used assembly today for time of flight measurements</li></ul>

**EBIT:** Alain Lapierre, Thomas Brunner, Christian Champagne, Josef Berger, Cecilia Leung

Einzel lens	<ul style="list-style-type: none"><li>- Status mainly unchanged.</li><li>- Anticipate Sikler/Einzel lens return from shop next Tuesday.</li><li>- Then vent, align, pump out, run EBIT</li></ul>
Detector	<ul style="list-style-type: none"><li>- Model is ready</li><li>- Revise machine drawings with Mel before sending them into machine shop</li></ul>
PIPS	<ul style="list-style-type: none"><li>- Tested, pre-amplifier doesn't work</li><li>- Closed vacuum tube to pump</li><li>- Got signal from detected e<sup>-</sup>, now working</li></ul>

**MPET:** Vladimir Ryjkov, Maxime Brodeur, Alexei Bylinskii

MPet	<ul style="list-style-type: none"><li>- Changed vacuum system with proper control system</li><li>- Found leak in joint we didn't open, replaced gasket, performed leak test. Pressure = 10<sup>-9</sup> now (back to where it was)</li><li>- e<sup>-</sup> gun verified working before, now see if MCP &amp; e<sup>-</sup> gun work in tandem.</li><li>- MCP flooded at first, now try to properly bias drift tubes</li><li>- Detecting 10<sup>4</sup> - &lt;10<sup>6</sup> ions/sec. (less than expected)</li><li>- Working in DC mode- create lots of space charge.</li><li>- Critical item: HV amplifier- pulse e<sup>-</sup> beam → noise issues source = ripple from DC power supply fast oscillations correspond to peak of ripple (0.5V) solution: by-pass power supply, increase capacitance at amplifiers</li></ul>
------	--

### Scientific Experiments:

Behlke-switch	- Completed & tested to 300V, looked clean
RFQ-MPET beamline	- Next step = transmission output of RFQ - Faraday cup right around corner detects beam profile is round; close to what we expect
Data acquisition	- Profile left over from last year; with Susanne - Difficult to clean up signal, try using frequency ram. (swift cleaning not recommended: didn't work well at MSU/Isol-trap) - Concentrate on step ramp- gives us quadruple excitation and burst